


# RECORD OF SURVEY No. 31-32

LOCATED IN THE SE 1/4 OF SEC. 20, THE NE 1/4 OF SEC 29, THE SW 1/4 OF SEC 21.  
AND THE NW 1/4 OF SEC 28 ,T8N, R23E, MDB&M, MONO COUNTY, CALIFORNIA


## SURVEYOR'S STATEMENT

THIS MAP CORRECTLY REPRESENTS A SURVEY MADE BY ME OR UNDER MY DIRECTION IN CONFORMANCE WITH THE REQUIREMENTS OF THE LAND SURVEYOR'S ACT AT THE REQUEST OF MIKE MAY IN AUGUST 1997



## COUNTY SURVEYOR'S STATEMENT

THIS MAP HAS BEEN EXAMINED IN ACCORDANCE WITH SECTION 8766 OF THE LAND SURVEYOR'S ACT THIS 4TH DAY OF FEB., 19 98



## RECORDER'S CERTIFICATE

FILED THIS 5th DAY OF February, 19 98 AT 4:28 P.M. IN BOOK 3 OF Maps, AT PAGE 59 AT THE REQUEST OF MIKE MAY.

Debra M. Miller  
COUNTY RECORDER Deputy

BASIS OF BEARINGS:  
N01°32'00"W, THE BEARING BETWEEN THE 1/4 CORNER S29/S28 (POINT 3 HEREON) AND THE SEC. COR. S20/S21/S28/S29 (POINT 1 HEREON) AS SHOWN ON BOOK 1 OF RECORD OF SURVEY MAPS, PAGE 77. NOTE: MEASUREMENT TAKEN TO THE SEC. COR. (POINT 1) AS DETERMINED FROM PREVIOUS SURVEYS PRIOR TO THE DISTURBANCE OF SAID CORNER.

EXP. DATE: 6/30/99

### LEGEND

- ⊙ FOUND SECTION CORNERS AS DESCRIBED HEREON
- △ FOUND 3/8" DIA. REBAR, SUBSTANTIALLY CONFORMS TO PROPERTY CORNER LOCATION ACCEPTED AS PROPERTY CORNER PER MB 2/27. RESET WITH 1 1/2" DIA. ALUMINUM CAP INSCRIBED "LS5149" ON 5/8" DIA. REBAR.
- ⊙ SET 1 1/2" DIA. ALUMINUM CAP INSCRIBED "LS 5149" ON 5/8" DIA. REBAR.
- ⊙ FOUND 1/2" I.D. BENT IRON PIPE, ACCEPTED AS LOT CORNER PER RSMB 1/77. REMOVED AND RESET WITH 1 1/2" DIA. ALUMINUM CAP INSCRIBED "LS 5149" ON 5/8" DIA. REBAR.
- ⊙ FOUND 1" I.D. IRON PIPE, NO TAG, ACCEPTED AS LOT CORNER PER RSMB 1/77 AND CORNER RECORD PREPARED 3/10/97 ON FILE IN THE MONO COUNTY SURVEY OFFICE.
- FOUND 1 1/2" DIA. ALUMINUM CAP INSCRIBED "LS 5149" ON 5/8" DIA. REBAR. ACCEPTED PER CORNER RECORD PREPARED 3/10/97 ON FILE IN THE MONO COUNTY SURVEY OFFICE.
- r RECORD INFORMATION BASED ON MB 2/27 UNLESS OTHERWISE NOTED.
- m MEASURED INFORMATION

